SELVE

OXC - 0685

30 June 1,960

MEMORANDUM FOR THE RECORD

SUBJECT: Brief Summary of Problem Areas Raised

at OXCART Suppliers Meeting

- The following is a brief summary of matters requiring follow-up attention raised at the OXCART Suppliers meeting held at Lockheed on 24 June:
 - a. Lockheed has encountered problems in the titanium area resulting from a lack of knowledge of the effect on titanium of salt deposits from fingerprints in conjunction with certain heat treatments of materials or chlorine solutions used in cleaning titanium, etc. Also, Lockheed reported delays in titanium shipments due to high rates of rejections of materials by quality control inspectors at supplier plants.

ACTION: Lockheed is revising titanium handling procedures as new information becomes available. Mr. Johnson feels that delivery schedules of titanium will improve as suppliers gain experience in producing titanium required in accordance with Lockheed's rigid specifications.

b. Lockheed reviewed weights and is implementing a careful control program to hold down weights. All systems suppliers were enjoined to stress weight control measures in monitoring respective areas of responsibility.

ACTION: Constant review of weights and close monitoring by all suppliers and Project managers.

c. Lockheed reported a slippage in the delivery schedule of an ejector to Pratt & Whitney (from August to October 1960) due to delays in fabricating rings as a result of non-availability of proper material.

ACTION: Lockheed

25X1

d. The Minneapolis-Honeywell autopilot and controls program now is about 2 - 3 weeks behind schedule, but the time is recoverable. M-H states that original delivery schedule will be met as a result of an expected improvement in staffing in the M-H personnel area.

BESSUMENT NO./24 ACTION:	Project Headquarters:	Monitor schedule	recovery.
NU DHANUL IN CL. Sh. V	- 		
DECLASSIFICA	Rélease 2002/10/30 : CI	13 Conv	of 420
CLASS. CHANGAS TO: 12 " 1	(»F	anry — oury	UUODIES
MEXT REVIEW Approved For	Réfease 2002/10/30 : CIÀ	DR& B00879R001000	0020139-0
AUTHI ER 78-2			7020100
DATE: 8FW82			

Approved For Release 2002/10/30 : CIA-RDP81B00879R001000020139-0

OXC - 0685 Page 2	7
	25X1
ACTION: Lockheed, Pratt & Whitney,	
f. Weather data, temperatures and pressures, etc. are of particular importance in non-standard day performance areas:	
ACTION: (1) AWS pursue assiduously the collection of data in arctic areas. (2) Project Headquarters monitor closely Pratt and Whitney performance estimates as data becomes available.	
g. Lockheed is concerned about A-12 rendezvous problems relating to refueling tanker aircraft when radio silence is mandatory.	
ACTION: Lockheed and Project review nications equipment and techniques.	25X1
h. Mr. C.L. Johnson requires B-58 accident data reports.	
ACTION: Colonel Geary is in the process of obtaining reports.	
i. Lockheed and Minneapolis-Honeywell have an interface problem relating to which organization should furnish cables and connect for the I. G. system and the airframe.	ors
ACTION: Lockheed is preparing a cost proposal.	
j. Lockheed requests that ARC-51 communications equipment required for the A-12 aircraft be procured as GFE by Head-quarters. Lockheed suggests that Lockheed's requirements	
ACTION: Chief, Materiel, DPD (3 Conv. of (

25X1

OXC - 0685 Page 3

k. Perkin-Elmer has a problem concerning the stable platform and sensing the vertical reference. Lockheed urges that P &E accept pick-offs from the I. G. system rather than attempt to duplicate inputs.

ACTION: Lockheed must acquire and provide aircraft characteristics data prior to a follow-up meeting with P & E, M-H, and Lockheed. Meanwhile, P & E will continue to review the uncaging platform problem.

1. A press for fin production must be moved from Convair, San Diego, ASAP.

ACTION: C/Materiel and work for this movement.

25X1

m. The Perkin-Elmer scheduled to commence 18 July requires further coordination with Project Headquarters.

25X1

ACTION: is in contact with of P & E regarding tests and test equipment requirements.

25X1

n. Pilots for OXCART should be brought about mid-1961 and available to meet the delivery of A-12 aircraft #3.

ACTION: Project Headquarters coordinate with Colonel Geary, General Flickinger and Lockheed.

o. Mr. Bissell affirmed that A-12 aircraft #3 should be modified as a two-seat aircraft.

ACTION: Mr. C. L. Johnson will submit a cost proposal.

p. Pratt & Whitney still has no solution to problems relating to sudden engine thrust decay when one engine flames out or is shut down during flight.

ACTION: Pratt & Whitney

q. Minneapolis-Honeywell is concerned about temperatures in the inertial guidance system equipment area in the event that a single engine is shut down for prolonged periods during flight. Gyroscopes will cease to function properly unless design specification temperature ranges are met.

ACTION: of Lockheed is to determine if some special cooling can be supplied to M-H equipment on an emergency basis.

Copy of 13 Copies

25X1

25X1

25X1

Approved For Release 2002/10/30 : CHA-RDP81B00879R001000020139-0

OXC - 0685 Page 4	л 25X1
	25/
8. Perkin-Elmer reported that RV7 clear for the games and a	
s. Perkin-Elmer reported that BK7 glass for the first flyable camera system was found to be unacceptable. Glass from the test system will be substituted temporarily in the first flyable system in order to meet schedules.	
ACTION: Perkin-Elmer monitor glass schedules	25X1
t. Mr. Bissell announced that suppliers should be prepared to support staging operations of short duration from or from bases in the Mid or Far East. In this regard, suppliers were directed to review spares, test and support equipment, test site and field organization requirements.	25 X1
ACTION: A meeting of supplier and Headquarters support personnel will be held in late July to review requirements. Results of this meeting will be reviewed briefly at the next general suppliers meeting.	
u. Mr. Bissell desires to review base site logistics and acceptance SOP's prepared by C/Materiel and	25X1
ACTION: C/Materiel, DPD	
v. Draft #3 of OXCART Cover Pian was reviewed. Suppliers were directed to submit reports within a month in writing on anticipated cover problems and suggested cover stories relating to respective areas for review by the Project Cover and Security Officer.	
ACTION: All suppliers/Cover and OXCART Security Officer	

13 Copy of 13 Copies

´ Approved For Release 2002/10/30 : CIA-RDP81B00879R001000020139-0

000 - 0685Page 5

25X1

2. The next regular OXCART suppliers meeting, to be held at Pratt and Whitney, Florida, is being programmed for mid or late August 1960.

JOHN PARANGOSKY Acting Chief, Development Branch DPD-DD/P

Distribution:

Copy 1 - DD/P

2 - AC/DPD

3 - ASST CH/DPD 4 - Admin/DPD

5 - Secur/DPD 6 - Cover/DPD

7 - DB/DPD 8 - Mat/DPD

9 - Ops/DPD

10 - Contr/DPD

11-12 - CH/DB/DPD 13 - RI/DPD

13 Copy of 13 Copies

